

Solvespace - Menus and Keyboard Shortcuts

File

New	Ctrl+N
Open ...	Ctrl+O
Open Recent	
Save	Ctrl+S
Save as ...	
Export Image ...	
Export 2D View ...	
Export 2D Section ...	
Export 2D Wireframe ...	
Export Triangle Mesh ...	
Export Surfaces ...	
Exit	

Edit

Undo	Ctrl+Z
Redo	Ctrl+Y
Regenerate All	Space
Snap Selection to Grid	.
Rotate Imported 90°	9
Cut	Ctrl+X
Copy	Ctrl+C
Paste	Ctrl+V
Paste Transformed	Ctrl+T
Delete	Del
Select Edge Chain	Ctrl+E
Select All	Ctrl+A
Unselect All	Esc

View

Zoom In	+
Zoom Out	-
Zoom To Fit	F
Align View to Workplane	W
Nearest Ortho View	F2
Nearest Isometric View	F3
Center at View Point	F4
Show Snap Grid	>
Use Perspective Projection	`
Show Text Window	Tab
Show Toolbar	
Dimension in Inches	
Dimension in Millimeters	

New Group

Sketch in 3D	Shift+3
Sketch in New Workplane	Shift+W
Step Translating	Shift+T
Step Rotating	Shift+R
Extrude	Shift+X
Lathe	Shift+L
Import / Assemble	Shift+I
Import Recent	

Sketch

In Workplane	2
Anywhere in 3D	3
Datum Point	P
Workplane	
Line Segment	S
Rectangle	R
Circle	C
Arc of a Circle	A
Bezier Cubic Spline	B
Text in True Type Font	T
Toggle Construction	G
Tangent Arc at Point	Shift+A
Split Curves at Intersection	I

Constrain

Distance / Diameter	D
Angle	N
Other Supplementary Angle	U
Toggle Reference Dim	E
Horizontal	H
Vertical	V
On Point / Curve / Plane	O
Equal Length / Radius / Angle	Q
Length Ratio	Z
At Midpoint	M
Symmetric	Y
Parallel / Tangent	L
Perpendicular	[
Same Orientation	X
Lock Point Where Dragged]
Comment	;

Analyze

Measure Volume	Ctrl+Shift+V
Mesure Area	Ctrl+Shift+A
Show Interfering Parts	Ctrl+Shift+I
Show Naked Edges	Ctrl+Shift+N
Show Degrees of Freedom	Ctrl+Shift+F
Trace Point	Ctrl+Shift+T
Stop Tracing ...	Ctrl+Shift+S
Step Dimension ...	Ctrl+Shift+D

Help

Website / Manual	
About	